

OKI Printer Driver Compatibility

Compatibility with Mac OS X

Mac OS X (10.13) High Sierra

Version: 1.8

Date: 2020-04-27

OKI Printer Driver Compatibility with Mac OS X High Sierra (10.13)

It is our aim at OKI that our customers have the best experience with our printers and multifunctional products when connected to PCs running Mac OS X.

The document below provides an overview of compatibility details of OKI printer drivers and utilities with Mac OS X

>> OKI Printer Driver Compatibility with Mac OS X - Rev.x.x

OKI are testing continuously with the new operating system and will update this document regularly.

If your printer model is not yet listed, please contact your local OKI support representative.

1. OKI PRINTER DRIVER COMPATIBILITY WITH MAC OS X



Model	Driver	OS X 10.13 High Sierra	Notes
B2200	GDI	not supported	
B2400	PCL	not supported	
B401	PCL	supported	
B410	PCL	supported	
B4100	PCL	not supported	
B411	PCL	supported	
B412	PCL	supported	
B420	PCL	supported	OKI PCL Driver Updater needed
B4250	PCL	not supported	
B430	PS	supported	OKI PCL Driver Updater needed
B430	PCL	supported	
B4300	PCL	not supported	
B4300	PS	not supported	
B431	PCL	supported	
B431	PS	supported	OKI PS Driver Updater needed (Note1)
B432	PCL	supported	(Note1)
B432	PS	supported	
B4350	PCL	not supported	
B4350	PS	not supported	

1. OKI PRINTER DRIVER COMPATIBILITY WITH MAC OS X



Model	Driver	OS X 10.13 High Sierra	Notes
B440	PS	supported	OKI PS Driver Updater needed
B440	PCL	supported	
B4400	PCL	supported	
B4500	PCL	supported	
B4500n	PCL	supported	
B4550	PCL	supported	OKI PCL Driver Updater needed
B4550n	PCL	supported	OKI PCL Driver Updater needed
B4600	PS	supported	OKI PS Driver Updater needed
B4600n	PS	supported	OKI PS Driver Updater needed
B512	PCL	supported	
B512	PS	supported	
B6100		not supported	
B6200		not supported	
B6250		not supported	
B6300		not supported	
B6500		not supported	
B710		not supported	
B720		not supported	
B721	PS	supported	

1. OKI PRINTER DRIVER COMPATIBILITY WITH MAC OS X



Model	Driver	OS X 10.13 High Sierra	Notes
B730		not supported	
B731	PS	supported	
B840	PCL	supported	
B840	PS	supported	OKI PS Driver Updater needed
B930		not supported	
C110	GDI	not supported	only Windows driver
C130	PS	not supported	
C301	Hiper-C	supported	
C310	Hiper-C	supported	
C3100	Hiper-C	not supported	only Windows driver
C3200	Hiper-C	not supported	only Windows driver
C321	PS	supported	OKI PS Driver Updater needed (Note1)
C330	PS	supported	OKI PS Driver Updater needed
C3300	Hiper-C	supported	
C331	PS	supported	OKI PS Driver Updater needed (Note1)
C332	PS	supported	
C3400	Hiper-C	supported	
C3450	Hiper-C	supported	
C3520MFP	Hiper-C	supported	

1. OKI PRINTER DRIVER COMPATIBILITY WITH MAC OS X



Model	Driver	OS X 10.13 High Sierra	Notes
C3530MFP	Hiper-C	supported	
C3600	PS	supported	OKI PS Driver Updater needed
C510	Hiper-C	supported	
C5100	Hiper-C	not supported	Windows only
C511	Hiper-C	supported	
C5200	Hiper-C	not supported	
C5250	Hiper-C	not supported	
C530	PS	supported	OKI PS Driver Updater needed
C5300	PS	not supported	
C531	PS	supported	OKI PS Driver Updater needed (Note1)
C532	PS	supported	
C5400	PS	not supported	
C542	PS	supported	
C5510nMPF	Hiper-C	not supported	
C5540MPF	PS	not supported	
C5550MFP	PS	not supported	
C5600	Hiper-C	supported	
C5650	Hiper-C	supported	
C5700	PS	not supported	

1. OKI PRINTER DRIVER COMPATIBILITY WITH MAC OS X



Model	Driver	OS X 10.13 High Sierra	Notes
C5750	PS	supported	OKI PS Driver Updater needed
C5800	Hiper-C	supported	
C5850	Hiper-C	supported	
C5900	PS	not supported	
C5950	PS	supported	OKI PS Driver Updater needed
C6000	PS	not supported	
C610	PS	supported	OKI PS Driver Updater needed
C6100	PS	not supported	
C612	PS	supported	
C710	PS	not supported	
C7100	PS	not supported	
C711	PS	supported	OKI PS Driver Updater needed
C711WT	PS	supported	
C712	PS	supported	
C7200	PS	not supported	
C7300	PS	not supported	
C7350	PS	not supported	
C7400	PS	not supported	
C7500	PS	not supported	

1. OKI PRINTER DRIVER COMPATIBILITY WITH MAC OS X



Model	Driver	OS X 10.13 High Sierra	Notes
C801	Hiper-C	supported	
C810	Hiper-C	supported	
C813	PS	supported	
C821	PS	supported	OKI PS Driver Updater needed
C822	PCL	supported	
C823	PCL	supported	
C824	PCL	supported	
C830	PS	supported	OKI PS Driver Updater needed
C831	PS	supported	OKI PS Driver Updater needed (Note1)
C833	PS	supported	
C834	PS	supported	
C841	PS	supported	OKI PS Driver Updater needed (Note1)
C843	PS	supported	
C844	PS	supported	
C8600	Hiper-C	not supported	
C8800	PS	supported	OKI PS Driver Updater needed
C910	PS	supported	OKI PS Driver Updater needed
C911	PS	supported	
C9200	PS	not supported	

1. OKI PRINTER DRIVER COMPATIBILITY WITH MAC OS X



Model	Driver	OS X 10.13 High Sierra	Notes
C920WT	PS	supported	
C9300	PS	not supported	
C931	PS	supported	
C931	PS (for Fiery C9 Server)	supported	
C9400	PS	not supported	
C941	PS	supported	
C941	PS (for Fiery C9 Server)	supported	
C942	PS	supported	
C942	PS (for Fiery C9 Server)	supported	
C9500	PS	not supported	
C9600	PS	not supported	
C9650	PS	supported	OKI PS Driver Updater needed
C9800	PS	not supported	
C9800MPF	PS	not supported	
C9850	PS	supported	
C9850MPF	PS	supported	
ES1624	PS	not supported	
ES1624MPF	PS	supported	OKI PS Driver Updater needed
ES2032	PS	not supported	

1. OKI PRINTER DRIVER COMPATIBILITY WITH MAC OS X



Model	Driver	OS X 10.13 High Sierra	Notes
ES2032MPF	PS	not supported	
ES2232	PS	supported	OKI PS Driver Updater needed
ES2632	PS	not supported	
ES2632	PS	supported	OKI PS Driver Updater needed
ES2632a3	PS	supported	OKI PS Driver Updater needed
ES3032a4	PS	not supported	
ES3451MPF	PS	supported	OKI PS Driver Updater needed
ES3451MPF	Scanner(ICA)		Push Scan NG under survey
ES3452MPF	PS	supported	OKI PS Driver Updater needed
ES3452MPF	Scanner(ICA)		Push Scan NG under survey
ES3461MPF	PS	supported	OKI PS Driver Updater needed
ES3461MPF	Scanner(ICA)		Push Scan NG under survey
ES3640	PS	not supported	
ES3640a3	PS	supported	OKI PS Driver Updater needed
ES3640pro	PS	supported	
ES3640ProMPF	PS	supported	
ES4131	PCL	supported	
ES4131	PS	supported	OKI PS Driver Updater needed (Note1)
ES4132	PCL	supported	

1. OKI PRINTER DRIVER COMPATIBILITY WITH MAC OS X



Model	Driver	OS X 10.13 High Sierra	Notes
ES4132	PS	supported	
ES4140dn	PS	supported	OKI PS Driver Updater needed
ES4140dn	PCL	supported	
ES4160MFP	PCL	supported	
ES4160MFP	Scanner(ICA)		Push Scan NG under survey
ES4161MFP	PCL	supported	
ES4161MFP	Scanner(ICA)		Push Scan NG under survey
ES4180MFP	PCL	supported	
ES4180MFP	PS	supported	OKI PS Driver Updater needed
ES4191MFP	PCL	supported	
ES4191MFP	PS	supported	Note1
ES4191MFP	Scanner(ICA)		Push Scan NG under survey
ES4192MFP	PCL	supported	
ES4192MFP	PS	supported	
ES4192MFP	Scanner(ICA)		Push Scan NG under survey
ES5112	PCL	supported	
ES5112	PS	supported	
ES5162MFP	PCL	supported	
ES5162MFP	PS	supported	

1. OKI PRINTER DRIVER COMPATIBILITY WITH MAC OS X



Model	Driver	OS X 10.13 High Sierra	Notes
ES5162MFP	Scanner(ICA)		Push Scan NG under survey
ES5430	PS	supported	OKI PS Driver Updater needed
ES5431dn	PS	supported	OKI PS Driver Updater needed (Note1)
ES5432	PS	supported	
ES5442	PS	supported	
ES5460MFP	PS	supported	OKI PS Driver Updater needed
ES5461MPF	PS	supported	OKI PS Driver Updater needed
ES5461MPF	Scanner(ICA)		Push Scan NG under survey
ES5462MPF	PS	supported	OKI PS Driver Updater needed
ES5462MPF	Scanner(ICA)		Push Scan NG under survey
ES5463MPF	PS	supported	
ES5463MPF	Scanner(ICA)		Push Scan NG under survey
ES5473MPF	PS	supported	
ES5473MPF	Scanner(ICA)		Push Scan NG under survey
ES6150		not supported	
ES6410	PS	supported	OKI PS Driver Updater needed
ES6412	PS	supported	
ES7131	PS	supported	
ES7170MFP	PS	supported	

1. OKI PRINTER DRIVER COMPATIBILITY WITH MAC OS X



Model	Driver	OS X 10.13 High Sierra	Notes
ES7411	PS	supported	OKI PS Driver Updater needed
ES7411WT	PS	supported	
ES7412	PS	supported	
ES7460MPF	PS	not supported	
ES7470MFP	PS	supported	
ES7480MFP	PS	supported	
ES8140	PCL	supported	OKI PCL Driver Updater needed
ES8140	PS	supported	OKI PS Driver Updater needed
ES8140dn	PCL	supported	OKI PCL Driver Updater needed
ES8140dn	PS	supported	OKI PS Driver Updater needed
ES8430dn	PS	supported	OKI PS Driver Updater needed
ES8431dn	PS	supported	OKI PS Driver Updater needed (Note1)
ES8433	PS	supported	
ES8434	PS	supported	
ES8441dn	PS	supported	OKI PS Driver Updater needed (Note1)
ES8451MPF	PS	supported	OKI PS Driver Updater needed
ES8451MPF	Scanner(ICA)		Push Scan NG under survey
ES8453	PS	supported	
ES8453	Scanner(ICA)		Push Scan NG under survey

1. OKI PRINTER DRIVER COMPATIBILITY WITH MAC OS X



Model	Driver	OS X 10.13 High Sierra	Notes
ES8460	PS	supported	OKI PS Driver Updater needed
ES8460	Scanner(ICA)		Push Scan NG under survey
ES8460MPF	PS	supported	OKI PS Driver Updater needed
ES8460MPF	Scanner(ICA)		Push Scan NG under survey
ES8461MPF	PS	supported	OKI PS Driver Updater needed
ES8461MPF	Scanner(ICA)		Push Scan NG under survey
ES8462	PS	supported	OKI PS Driver Updater needed (Note1)
ES8462	Scanner(ICA)		Push Scan NG under survey
ES8473MPF	PS	supported	
ES8473MPF	Scanner(ICA)		Push Scan NG under survey
ES9130		not supported	
ES9160MFP	PS	not supported	
ES9170MFP	PS	not supported	
ES9410	PS	supported	OKI PS Driver Updater needed
ES9411	PS	supported	
ES9420WT	PS	supported	
ES9455MPF	PS	not supported	
ES9460MPF	PS	not supported	
ES9465MPF	PS	not supported	

1. OKI PRINTER DRIVER COMPATIBILITY WITH MAC OS X



Model	Driver	OS X 10.13 High Sierra	Notes
ES9466MPF	PS	supported	
ES9470MPF	PS	not supported	
ES9475MPF	PS	not supported	
ES9476MPF	PS	supported	
ES9541	PS	supported	
ES9541	PS (for Fiery C9 Server)	supported	
ES9542	PS	supported	
ES9542	PS (for Fiery C9 Server)	supported	
MB260		not supported	
MB280		not supported	
MB290		not supported	
MB441	PCL	supported	
MB441	Scanner(ICA)		Push Scan NG under survey
MB451	PCL	supported	
MB451	PS	supported	Note1
MB451	Scanner(ICA)		Push Scan NG under survey
MB460	PCL	supported	
MB460	Scanner(ICA)		Push Scan NG under survey
MB461	Scanner(ICA)		Push Scan NG under survey

1. OKI PRINTER DRIVER COMPATIBILITY WITH MAC OS X



Model	Driver	OS X 10.13 High Sierra	Notes
MB461d	PCL	supported	
MB470	PCL	supported	
MB470	PS	supported	OKI PS Driver Updater needed
MB471	PCL	supported	
MB471	PS	supported	Note1
MB471	Scanner(ICA)		Push Scan NG under survey
MB472	PCL	supported	
MB472	Scanner(ICA)		Push Scan NG under survey
MB480	PCL	supported	
MB480	PS	supported	OKI PCL Driver Updater needed
MB491	PCL	supported	
MB491	PS	supported	Note1
MB491	Scanner(ICA)		Push Scan NG under survey
MB492	PCL	supported	
MB492	PS	supported	
MB492	Scanner(ICA)		Push Scan NG under survey
MB562	PCL	supported	
MB562	PS	supported	
MB562	Scanner(ICA)		Push Scan NG under survey

1. OKI PRINTER DRIVER COMPATIBILITY WITH MAC OS X



Model	Driver	OS X 10.13 High Sierra	Notes
MB760	PS	supported	
MB770	PS	supported	
MC160MPF	GDI	not supported	
MC160MPF	Scanner	not supported	
MC160n	GDI	not supported	
MC160n	Scanner	not supported	
MC332	PS	supported	OKI PS Driver Updater needed
MC332	Scanner(ICA)		Push Scan NG under survey
MC342	PS	supported	OKI PS Driver Updater needed
MC342	Scanner(ICA)		Push Scan NG under survey
MC350	Hiper-C	supported	
MC351	PS	supported	OKI PS Driver Updater needed
MC351	Scanner(ICA)		Push Scan NG under survey
MC352	PS	supported	OKI PS Driver Updater needed
MC352	Scanner(ICA)		Push Scan NG under survey
MC360	Hiper-C	supported	
MC361	PS	supported	OKI PS Driver Updater needed
MC361	Scanner(ICA)		Push Scan NG under survey
MC362	PS	supported	OKI PS Driver Updater needed

1. OKI PRINTER DRIVER COMPATIBILITY WITH MAC OS X



Model	Driver	OS X 10.13 High Sierra	Notes
MC362	Scanner(ICA)		Push Scan NG under survey
MC363	PS	supported	
MC363	Scanner(ICA)		Push Scan NG under survey
MC560	PS	supported	OKI PS Driver Updater needed
MC561	PS	supported	OKI PS Driver Updater needed
MC561	Scanner(ICA)		Push Scan NG under survey
MC562	PS	supported	OKI PS Driver Updater needed
MC562	Scanner(ICA)		Push Scan NG under survey
MC563	PS	supported	
MC563	Scanner(ICA)		Push Scan NG under survey
MC573	PS	supported	
MC573	Scanner(ICA)		Push Scan NG under survey
MC760	PS	supported	
MC770	PS	supported	
MC780	PS	supported	
MC851	PS	supported	OKI PS Driver Updater needed
MC851	Scanner(ICA)		Push Scan NG under survey
MC852	Scanner(ICA)		Push Scan NG under survey
MC852	PS	supported	OKI PS Driver Updater needed (Note1)

1. OKI PRINTER DRIVER COMPATIBILITY WITH MAC OS X



Model	Driver	OS X 10.13 High Sierra	Notes
MC853	PS	supported	
MC853	Scanner(ICA)		Push Scan NG under survey
MC861	PS	supported	OKI PS Driver Updater needed
MC861	Scanner(ICA)		Push Scan NG under survey
MC862	PS	supported	OKI PS Driver Updater needed (Note1)
MC862	Scanner(ICA)		Push Scan NG under survey
MC873	PS	supported	
MC873	Scanner(ICA)		Push Scan NG under survey
OKIPAGE 14	PCL	not supported	
OKIPAGE 18	PCL	not supported	
OKIPAGE 18	PS	not supported	
Pro6410 NeonColor	PS	supported	
Pro7411WT	PS	supported	
Pro8432WT	PS	supported	
Pro9420WT	PS	supported	
Pro9431	PS	supported	
Pro9431	PS (for Fiery C9 Server)	supported	
Pro9541	PS	supported	
Pro9541	PS (for Fiery C9 Server)	supported	

1. OKI PRINTER DRIVER COMPATIBILITY WITH MAC OS X



Model	Driver	OS X 10.13 High Sierra	Notes
Pro9541WT	PS	supported	
Pro9542	PS	supported	
Pro9542	PS (for Fiery C9 Server)	supported	

Note	Description
1	Printer driver uninstallers may not be opened. Follow the below procedure to open. (1) Click [Control] - Click the software icon. (2) Click [Open] from the pop-up menu. (3) Click [Open] in the next window.

2. OKI SOFTWARE UTILITY COMPATIBILITY WITH MAC OS X



Driver	OS X 10.13 High Sierra	Notes
CANAL	supported	
Cloud Support	supported	
Color Collect Utility C301, C310, C312, C321, C330, C3300, C331, C3400, C3450, C3520MFP, C3530MFP, C3600, C510, C511, C530, C531, C5500, C5600, C5650, C5750, C5800, C5850, C5950, C6050, C610, C6150, C711, C801, C810, C821, C830, C831, C841, C8800, C910, C911, C931, C941, C9650, C9655, ES2232, ES2632a3, ES2632a4, ES3451MFP, ES3452MFP, ES3461MFP, ES3640a3, ES5430, ES5431, ES5461MFP, ES5462MFP, ES6410, ES7411, ES8430, ES8431, ES8441, ES8451MFP, ES8460MFP, ES8461MFP, ES9410, ES9411, ES9431, ES9541, MC332, MC342, MC350, MC351, MC352, MC360, MC361, MC362, MC561, MC562, MC851, MC860, MC861	supported	
Command Workstation 5		Please confirm the following URL: http://www.efi.com/products/fiery-servers-and-software/fiery-command-workstation/fiery-command-workstation/overview/
FW Update Tool	supported	
Fiery Unidriver		under consideration
Menu setup for B2000 Series	not supported	

2. OKI SOFTWARE UTILITY COMPATIBILITY WITH MAC OS X



Driver	OS X 10.13 High Sierra	Notes
Menu setup for B400 Series	supported	
Menu setup for B4000 Series		
Menu setup for B411	supported	
Menu setup for B4400 Series	not supported	
Menu setup for C3100	not supported	
Menu setup for C3200	not supported	
Menu setup for C3300	supported	
Menu setup for C3400	supported	
Menu setup for C3450	supported	
Menu setup for ML22L	not supported	
NIC Setup Tool	supported	
Panel Language Downloader	supported	
Parameter Tool	supported	
Print Job Accounting Client	supported	

2. OKI SOFTWARE UTILITY COMPATIBILITY WITH MAC OS X



Driver	OS X 10.13 High Sierra	Notes
Profile Assistant	supported	
PS Gamma Adjuster	supported	